Panasonic

WV-X4173/X4172/X4573L(M)/S4151/S4551L(M) firmware

Contents

Priority Rank Level
A: Recommend to apply (Major or serious update)
B: When issue happened
C: Maintenance timing
U: Function /Performance improvement (Not Necessary to update)

WV-X4173 WV-X4172 WV-X4573L(M)	WV-S4151 WV-S4551L(M)	Priority Rank Level	A	B	C	U	Issue (Phenomenon)	Occurrence condition	Correspondence
New models added on Feb. 8, 2021									
Ver1.00 (4.60.03) Jan.,'21	Ver1.00 (4.60.03) Feb.,'21	-					First production.		
Ver1.01 (4.60.03) Jan.,'21	Ver1.01 (4.60.03) Feb.,'21	C				x	The camera may start recording outside of scheduled time when it is booted. (Occurrence frequency: Rare)	When SD recording is scheduled	Fixed.
	Added on Feb. 8, 2021 Ver1.02 (4.60.03) Feb.,'21	C				x	-	-	Improved the image quality as below: - Image noise on a face under high illuminance condition - Image lag under low illuminance condition - Signal-to-noise ratio when the illuminance changes from normal to low level
Ver1.02 (4.60.03) Jan.,'21						x	-	-	Improved the image quality when shooting outside under low illuminance condition.
	Ver1.02 (4.60.03) Feb.,'21					x	Image distortion may occur in the Single PTZ screen. (Occurrence frequency: Low)	-	Fixed.
Ver1.40 (4.60.03) Mar.,'21	Ver1.40 (4.60.03) Mar.,'21	C				x	-	-	Improved the response to the CGI command "/cgi-bin/get_io2" by adding VMD ratio in percentage.
						x	-	-	Changed the default setting of [Network Settings] in [Setup]-> [Network] page-> [Network] tab, from "Auto(Advanced)" to "DHCP".
						x	-	-	Added the On/Off setting for the Secure Real-time Transport Protocol (SRTP) function to the [Advanced] tab in [Setup]-> [Network] page.
						x	-	-	Improved the [HTTP alarm notification] function as follows: 1. Supports Digest authentication - The camera performs either "Digest" or "Basic" authentication according to the response from the HTTP server when initially accessed without ID and password. 2. Adds an error log for the failure in HTTP server user authentication - Displays "<HTTP alarm notification> authentication error" in the system log when the authentication fails. 3. Supports HTTPS Communication - Entering "https://" in [Address] enables HTTPS communication.
						x	-	-	Added the On/Off setting for ONVIF® to the [Network] tab in [Setup]-> [Network] page. (Default : On)
						x	-	-	Enabled both digital certificates "Digicert" and "GlobalSign". Note: Firmware upgrade does not change the certificate in a camera. Click here for further information in case of SSL communication.
						x			Supports the change of audio codec IC in a camera. Note: Audio will not work if the camera installed new IC is downgraded to version 1.30 or older.

Panasonic

This document describes WV-X4173 firmware upgrade Info.
1. Release version： Version 1.40
2. Release Note Reference Number：X4173-002

WV-X4173/X4172/X4573L(M)/S4151/S4551L(M) firmware

WV-X4173 WV-X4172 WV-X4573L(M) / New models added on Feb. 8, 2021	WV-S4151 WV-S4551L(M)	Priority Rank Level	Priority Rank Level A: Recommend to apply (Major or serious update) B: When issue happened C: Maintenance timing U: Function /Performance improvement (Not Necessary to update)				Contents		
			A	B	C	U	Issue (Phenomenon)	Occurrence condition	Correspondence
Ver1.40 (4.60.03) Mar.,'21	Ver1.40 (4.60.03) Mar.,'21	C			x		-	-	Corrected the RTSP protocol for transmitting H.265 images using ONVIF®.
					x		UDP communication may be disconnected depending on the network environment. (Occurrence frequency: Rare)	When transmitting high resolution or high bit rate images.	Fixed.
						x	-	-	Enhanced security.
					x		The audio may not work or the left and right sound may be reversed. (Occurrence frequency: Rare)	When the camera starts at low tenperature.	Fixed.
						x	-	-	Changed the notification message* of frame rate reduction as below: from "Frame thinning display" to "Reduced frame mode" *Camera displays this message when: - streaming the H.265 / H.264 image - viewing live images in Google Chrome, Microsoft Edge, and Moriza Firefox
					x		The camera may show a black image. (Occurrence frequency: Rare)	When the setting in [Image capture size] or [Image capture mode] is changed repeatedly.	Fixed.
					x				Corrected the parameter of UtcTime attribute in ONVIF Metadata Analytics Stream.