



# Corrigenda

Installation Guide contain incorrect descriptions. Refer to the following table and confirm the descriptions that are corrected.



WV-X1571LN / WV-X1551LN / WV-X2571LN / WV-X2551LN / WV-S1572L / WV-S1552L / WV-S2572L / WV-S2552L / WV-X4573L / WV-S4551L / WV-X4573LM / WV-S4551LM

## Making connections

Incorrect	Correct
 <p>Audio input cable (white)</p> <p>Less than 10 m {32.8 feet} (for microphone input)</p> <p>Less than 1 m {3.28 feet} (for line input)</p>	 <p>Audio input cable (white)</p> <p>Less than <u>1 m {3.28 feet}</u> (for microphone input)</p> <p>Less than <u>10 m {32.8 feet}</u> (for line input)</p>

WV-X4173 / WV-S4151 / WV-X4172 / WV-X4573L / WV-S4551L / WV-X4573LM / WV-S4551LM

## Processing the installation surface (process according to the installation type)

Incorrect	Correct
	

WV-X4173 / WV-S4151 / WV-X4172

## Optional accessories

Incorrect	Correct
Corner mount bracket : WV-Q105A	Ceiling mount bracket : WV-Q105A

\* PGQW2317ZA \*



avs0121-0  
Printed in China