

This document describes WV-X5550LT/WV-X5550LTPJ firmware upgrade Info. 1. Release version: Version 2.00

2. Release Note Reference Number: X5550LT-003

WV-X5550LT and WV-X5550LTPJ Firmware Release Note

VER (ActiveX VER) Release Date	Priority Rank Level			ınk	Priority Rank Level A: Recommend to apply (Major or serious update) B: When issue happened C: Maintenance timing U: Function /Performance improvement (Not Necessary to update))	Contents	
		Α	В	U	Issue (Phenomenon)	Occur	rence condition	Correspondence
Ver1.00 (4.50.38) August,'20	-				First production			
Ver1.01 (4.50.38) Nov.,'20	U			x	-		-	Added the following parameters to the CGI command response, for the improvement in connectivity with the Video Management System(VMS) of Genetec and Milestone. - "video_server.image.sensor.number=1" for Single source - "video_server.image.sensor.number=2" for Dual sources
Ver2.00 (4.60.30) Apr., '22	U			х	-		-	Changed company name from "Panasonic i-PRO Sensing Solutions Co., Ltd." to "i-PRO Co., Ltd."
				x	-		-	Updated SNMP extended MIB: Changed the extended Object ID(OID) from Panasonic(258) to i-PRO(57501). Note: - This change applies only to the products manufactured in April, 2022* or later, and is not applied by firmware upgrade. *Serial number: VDxxxxxx - MIB file and manual are available at the following link: https://i-pro.com/global/en/surveillance/database/i-pro-device-integration/snmp-mib
				х	-		-	Changed the alarm name from "Panasonic alarm protocol notification" to "TCP alarm notification".

1/1 X5550LT-003