

## WJ-NX200 Firmware Release Note

VER (ActiveX Ver) Release Date	Priority Rank Level				U	Issue (Phenomenon)	Occurrence condition	Correspondence
	A	B	C					
Ver1.02 (6.0.15.0) June,'17	-					First production.		
Ver1.11 (6.0.20.0) Sept.,'17	C				x	-	-	Supported the Additional Business Intelligence Kit, WJ-NXF02.
					x	-	-	Supported MP4 file format for copy and download.
					x	-	-	Supported Audio AAC format.
					x	-	-	Supported Network Microphone, Model WV-SMR10 series.
					x	-	-	Added Time-saving playback function.
					x	-	-	Added layout of image capture size for corridor format.
					x	-	-	Supported the Compatible view function on Internet Explorer.
					x	-	-	Added a setting of frame rate/bit rate for substream.
					x	-	-	Supported new cameras; WV-S6111, WV-S6130, WV-S6131 and WV-S6530N
Ver2.00 (6.0.25.0) Jan.,'18	C				x	-	-	Supported WV-S4150, WV-S4550L and WV-S4550LM.
					x	-	-	Supported "Concurrent User License Kit". WJ-NXC05W must be installed to be controlled by WV-ASM300CLW.
					x	-	-	Supported HDD Viewer Software.
					x	-	-	<b>Supported Energy Efficient Ethernet (IEEE802.3az) Switch.</b> Improved not to correspond to IEEE 802.3az to prevent packet loss occur even if Energy Efficient Ethernet (IEEE802.3az) had not been disabled on the switch side.
						x	By displaying 1-screen live on main monitor with activating "Display 1-screen live image on stream 2".	Fixed.
Ver2.02 (6.0.25.0) Feb.,'18	B		x			While using with WV-S4150, WV-S4550L and WV-S4550LM, recording time (recording hours) may shorter than expected.	In case configurations are as follow; Compression: H.265(1) Smart coding (GOP control): On(Advanced) Image capture size: 5M(2192x2192) Image quality/Frame rate: One of FQ/1ips, NQ/1ips, NQ/3ips or NQ/5ips	Fixed.

## WJ-NX200 Firmware Release Note

VER (ActiveX Ver) Release Date	Priority Rank Level				Priority Rank Level A: Recommend to apply (Major or serious update) B: When issue happened C: Maintenance timing U: Function /Performance improvement (Not Necessary to update)	Contents		
	A	B	C	U		Issue (Phenomenon)	Occurrence condition	Correspondence
Ver2.20 (6.0.25.0) Apr.,'18	B				x	-	-	Supported new cameras; WV-X4171, WV-X4571L, WV-X4170, WV-X4171, WV-X4571L and WV-X4571LM
					x	-	-	Added user authentication method at accessing camera.
					x	-	-	Added Static Route function.
					x	-	-	Added function to display online user information.
					x	-	-	Possible to correct (move) camera frame position by manual when registering a face of the face collation function.
					x	-	-	Supported Intelligent auto function and back light compensation function on i-PRO EXTREME cameras.
					x	-	-	Supported holding position of fisheye correction after resuming from camera communication error.
			x				-	Fixed.
				x			-	Fixed.
			x		-	Fixed.		
Ver2.21 (6.0.25.0) June,'18	C				x	The recovery start log is not displayed in rare cases nor the hour meter of the replacement HDD may not display even though RAID recovery is started.	-	Fixed.
					x	Live video may be rarely mixed display or black screen by changing the browser 4 screen display changed when browsing on a high spec PC.	-	Fixed.
					x	The NX Viewer may terminate unexpectedly when viewing an N3R file with the Viewer.	-	Fixed.
					x	Texts of some screens are hardly displayed while selecting Portuguese, Thai or Chinese language.	-	Fixed.
Ver2.30 (6.0.28.0) July,'18	U				x		-	Support new cameras as follow; - WV-S8530N and WV-X8570N - WV-S1550L, WV-S2250L and WV-S2550L
					x		-	Added the camera partitioning function. Became ability to set displaying / operating camera for each user.
					x		-	Added a function to format HDDs without stopping recording.
					x		-	Added a function to remove HDDs without stopping recording.

## WJ-NX200 Firmware Release Note

VER (ActiveX Ver) Release Date	Priority Rank Level				Priority Rank Level A: Recommend to apply (Major or serious update) B: When issue happened C: Maintenance timing U: Function /Performance improvement (Not Necessary to update)	Contents		
	A	B	C	U		Issue (Phenomenon)	Occurrence condition	Correspondence
Ver2.30 (6.0.28.0) July,'18	U				x		-	Added a function to confirm password before removing HDDs.
					x		-	Added a function to inhibit an alarm pop-up a message.
					x		-	Added 24-screen in a choice of the setting items as new function.
					x		-	Support Digest authentication on WJ-GXE500.
					x		-	Changed the status display at adding new HDDs and/or external units from "Formatting HDD" to "Checking HDD".
					x		-	Improved to display a dialog message that losing registered settings by clicking the "New" button to detect camera if the cameras have already registered.
Ver2.40 (6.0.30.0) Nov.,'18	C				x		-	Improved NTP vulnerability.
					x	-	-	Support new cameras as follow; - WV-S3111L, WV-S3131L, WV-S3511L and WV-S3531L
					x	-	-	Changed password policy that it must include at least 3 types of characters among "upper case letters / lower case letters / numbers / symbols".
					x	-	-	Added a function to measure the size of data for network communication.
					x	-	-	Added function of displaying the remaining space and notification of the storage medium.
					x	-	-	Added a function of emergency recording.
					x	-	-	Added updating Dynamic DNS function.
					x	-	-	Added a settings to keep aspect ratio at wide view screen on main monitor.
					x	-	-	Added a choice of "Off"/"On" of "High quality mode" at the settings at the "Configure the mode" settings for "Face matching" and "Accumulate statistics data".
				x		Unable to act in associate with the command alarm numbers between 65 to 128.	-	Fixed.
					x		-	Improved displaying picture smoothly immediately after switching when sequencing one image with two high resolution cameras.
		x		The buzzer kept on sounding even after the event recording.	When setting "Buzzer duration" is "Rec." at "Alarm action" in "Event setup" tab.	Fixed.		
		x		Storage of various logs may fail.	After power interruption occur.	Fixed.		