

This document describes software package upgrade for WV-S3131L/S3111L/S3531L/S3511L/S3532LM/S3512LM.

1. Release version: 4.01  
2. Release Note Reference Number: S3531L\_002

| VER<br>(ActiveX VER)<br>Release Date | Priority Rank Level |   |   |   | Issue (Phenomenon)   | Occurrence condition   | Correspondence |
|--------------------------------------|---------------------|---|---|---|--|--|----------------|
|                                      | A                   | B | C | U |  |  |                |
| Ver4.00<br>(4.50.35)<br>Mar.,'19     |                     |   |   |   | First production.  |  |                |
| Ver4.01<br>(4.50.35)<br>Feb.,'19     | B                   |   |   | x | The oldest recorded data may not be able to play back.   | When the setting of overwrite recording to SD memory card is "On". | Fixed.         |
|                                      |                     |   |   | x | Communication may stop even if connected with a PC or switch after starting up by PoE injector or external power supply (24V AC / 12V DC). | -  | Fixed.         |