

WV-S3131L/S3111L/S3531L/S3511L/S3532LM/S3512LM Release Note

This document describes software package upgrade for WV-S3131L/S3111L/S3531L/S3511L/S3532LM/S3512LM.

1. Release version: 4.11
2. Release Note Reference Number: S3531L_004

VER (ActiveX VER) Release Date	Priority Rank Level				Issue (Phenomenon)	Occurrence condition	Correspondence
	A	B	C	U			
Ver4.00 (4.50.35) Mar.,'19					First production.		
Ver4.01 (4.50.35) Feb.,'19	B			x	The oldest recorded data may not be able to play back.	When the setting of overwrite recording to SD memory card is "On".	Fixed.
				x	Communication may stop even if connected with a PC or switch after starting up by PoE injector or external power supply (24V AC / 12V DC).	-	Fixed.
Ver4.10 (4.50.35) June,'19	C			x	-	-	Security has been enhanced.
				x	Audio may not output by attempting to connect two sessions simultaneously and failure to authenticate one of them.	-	Fixed.
				x	-	-	Added a note in the window of DDNS setting page when using "Dynamic DNS Update", "Dynamic DNS Update(DHCP)".
				x	-	-	Supported multi-browsers other than the Internet Explorer. Some restrictions apply: click here for details.
				x	-	-	Improved smooth text display by changing the texts on the screen from 2 gradations to grayscale.
				x	-	-	Added a CGI command to make an alarm; /Set?Func=SoftTrigger or /cgi-bin/Set?Func=SoftTrigger or /cgi-bin/comalarm.cgi
				x	-	-	Added interference detection information to additional information when using the i-VMD function of Extension software.
				x	-	-	Display the license of open source software (OSS) on upgrade screen.
				x	ONVIF communication may become a cause of destroying resources.	-	Fixed.
				x	-	-	Fixed Session Description Protocol/SDP (IPv6) on ONVIF.
				x	Unable to find ONVIF search.	-	Fixed.
				x	Improved the detection capability of "face with mask" at face detection in cooperation with Facial Recognition Server Software, WV-ASF 950 series and so on.	-	Fixed.
		x	-	-	The file may not be found by opening the log list during overwrite recording of the SD memory card and attempt to browse.		
		x	-	-	The camera may restart by encrypting the stream 1 only, selecting audio transmission mode AAC-LC and recording video and audio simultaneously.		

WV-S3131L/S3111L/S3531L/S3511L/S3532LM/S3512LM Release Note

This document describes software package upgrade for WV-S3131L/S3111L/S3531L/S3511L/S3532LM/S3512LM.

1. Release version: 4.11
2. Release Note Reference Number: S3531L_004

VER (ActiveX VER) Release Date	Priority Rank Level				Issue (Phenomenon)	Occurrence condition	Correspondence
	A	B	C	U			
Ver4.11 (4.50.35) July,'19	C			x	The face best-shot image used to display face search history data on Video Management Software may not be created correctly. (Occurrence frequency: Rare)	-	Fixed. Note: The cameras are NOT recommended to use the face best-shot function.
				x	The camera may restart when live sequence display by network disk recorder or Video Management Software without distributing H.264 or H.265 for recording. (Occurrence frequency: Rare)	-	Fixed.