

WV-S2570L/S2270L(H)/S1570L(H) Release Note

This document describes software package upgrade for WV-S2570L/S2270L(H)/S1570L(H).

1. Release version: 4.20
 2. Release Note Reference Number: S2570L_003

VER (ActiveX VER) Release Date	Priority Rank Level				Issue (Phenomenon)	Occurrence condition	Correspondence	
	A	B	C	U				
Ver1.00 (4.50.35) May,'19					First production.			
Ver1.00 (4.50.35) July,'19					Supported Chinese market models, WV-S2270LH and WV-S1570LH.			
Ver4.20 (4.50.35) Sept.,'19	C				x	-	In FTP / SNMP authentication, "Authentication error" is logged in the system log by failing authentication more than a certain condition.	
					x	-	Supported EasyIpSetup software (Ver4.31R00) and became to display serial numbers of devices.	
					x	-	Updated (Enhanced) SNMP MIB information. The document of i-PRO camera management information (MIB) is available at the following URL; https://bizpartner.panasonic.net/public/ppr/finder/107669?keyword=key_camera_mib&sort=last_modified&order=desc	
					x	-	Improved so that available to connect with HikVision recorder by CGI command.	
				x		ONVIF communication may become a cause of destroying resources.	-	Fixed.
				x		Camera may not be able to be found by the ONVIF search.	-	Fixed.
				x		One of the authentications failed and the sound could not be heard when attempting to connect two sessions at the same time.	-	Fixed.
					x	-	-	Added displaying a note on the screen at Service in the DDNS setting screen, when "Dynamic DNS Update" or "Dynamic DNS Update (DHCP)" is selected.
					x	-	-	Improved the characters display in the screen from 2 tones to grayscale for smooth display.
					x	-	-	Added a CGI command to occur alarm; /Set?Func=SoftTrigger or /cgi-bin/Set?Func=SoftTrigger or /cgi-bin/comalarm.cgi
			x	-	-	Added tamper detection information to additional information when using the function expansion software "i-VMD"		
			x	Unable to hear audio in both ONVIF and browser when setting the "Interactive(Half-duplex)" at Audio output and streaming AudioBackChannel in ONVIF.	-	Fixed.		
			x	The camera may restart due to memory access error. (Occurrence frequency: Rare)	-	Fixed.		

*: ONVIF is a trademark of Onvif, Inc.