

VER (ActiveX VER) Release Date	Priority Rank Level				Priority Rank Level A: Recommend to apply (Major or serious update) B: When issue happened C: Maintenance timing U: Function /Performance improvement (Not Necessary to update)	Contents		
	A	B	C	U		Issue (Phenomenon)	Occurrence condition	Correspondence
1.40 July, '18 <b>Deleted on Sept.17, 2019</b>				x	1st release for WV-ASF950.	-	-	<del>Improved from previous model that displaying the camera tree of the face search monitor correctly when creating a tree structure with multiple same cameras in the Genetec device tree.</del>
1.41 Dec., '18	B			x	Operation may not be able to done by scrolling face search result at Face search tab of Face search monitor function, repeatedly.	While using with WV-ASE231W.		Fixed.
			x		Display only 100 attribute information (from old one) instead of displaying up to 1,000 in the list of registered faces, and unable to edit the 101th and newer registered faces (no problems on 101th and newer face matching alarm notifications).	1. On version 1.00. 2. Using with WV-ASE231W and WV-ASF900. Note: Nothing problem combination with WV-ASE231W and WV-ASF950.		Fixed.
				x	A face image managed by a slave server may not be displayed.	On WV-ASE 231W is used, WV-ASF 950 is configured as master / slave server and encryption function is enabled.		Fixed.
				x	Name of realtime alarm and remarks on second unit (and after) may not displayed properly.			Fixed.
					x	-	-	
			x	-	-		<b>Improved displaying the camera tree of the face search monitor correctly when creating a tree structure with multiple same cameras in the Genetec device tree.</b>	
<del>1.42</del> <del>1.03</del> Apr., '18	U			x	-	-		Improved the GUI for product registration.
2.00 Aug., '19	U			x	-	-		Supported a new function, Unregistered Face Detection, on WV-ASF950 Ver2.00.