

WV-S2570L/S2270L(H)/S1570L(H) Release Note

This document describes software package upgrade for WV-S2570L/S2270L(H)/S1570L(H).

1. Release version: 4.21
 2. Release Note Reference Number: S2570L_004

VER (ActiveX VER) Release Date	Priority Rank Level				Issue (Phenomenon)	Occurrence condition	Correspondence		
	A	B	C	U					
Ver1.00 (4.50.35) May,'19					First production.				
Ver1.00 (4.50.35) July,'19					Supported Chinese market models, WV-S2270LH and WV-S1570LH.				
Ver4.20 (4.50.35) Sept.,'19	C				x	-	-	In FTP / SNMP authentication, "Authentication error" is logged in the system log by failing authentication more than a certain condition.	
						x	-	-	Supported EasyIpSetup software (Ver4.31R00) and became to display serial numbers of devices.
							x	-	Updated (Enhanced) SNMP MIB information. The document of i-PRO camera management information (MIB) is available at the following URL; https://security.panasonic.com/training_support/panasonic_device_integration/snmp-mib/
							x	-	Improved so that available to connect with HIKVision recorder by CGI command.
							x	-	ONVIF communication may become a cause of destroying resources.
							x	-	Camera may not be able to be found by the ONVIF search.
							x	-	One of the authentications failed and the sound could not be heard when attempting to connect two sessions at the same time.
							x	-	Added displaying a note on the screen at Service in the DDNS setting screen, when "Dynamic DNS Update" or "Dynamic DNS Update (DHCP)" is selected.
							x	-	Improved the characters display in the screen from 2 tones to grayscale for smooth display.
							x	-	Added a CGI command to occur alarm; /Set?Func=SoftTrigger or /cgi-bin/Set?Func=SoftTrigger or /cgi-bin/comalarm.cgi
							x	-	Added tamper detection information to additional information when using the function expansion software "i-VMD"
					x	-	Unable to hear audio in both ONVIF and browser when setting the "Interactive(Half-duplex)" at Audio output and streaming AudioBackChannel in ONVIF.		
					x	-	The camera may restart due to memory access error. (Occurrence frequency: Rare)		

Corrected on Nov. 8, 2019

*: ONVIF is a trademark of Onvif, Inc.

WV-S2570L/S2270L(H)/S1570L(H) Release Note

This document describes software package upgrade for WV-S2570L/S2270L(H)/S1570L(H).

1. Release version: 4.21
 2. Release Note Reference Number: S2570L_004

VER (ActiveX VER) Release Date	Priority Rank Level				Issue (Phenomenon)	Occurrence condition	Correspondence
	A	B	C	U			
Ver4.21 (4.50.35) Nov., '19	C			x	Rarely, the focus may not be optimum during autofocus operation when switching between Color and Black/White in low contrast environments such as low illuminance and point light source.	-	Fixed.
					-	-	Improved the convergence time of images from overexposure to optimal exposure in the backlight environment while Super Dynamic was "ON".

Priority Rank Level
 A: Recommend to apply (Major or serious update)
 B: When issue happened
 C: Maintenance timing
 U: Function /Performance improvement (Not Necessary to update)

*: ONVIF is a trademark of Onvif, Inc.